



32592 Valle Road, San Juan Capistrano, CA 92675
 Ph. 949-347-2522 Fax 949-218-2942
 BAR# ARD00274065

Invoice # A18473

JOHN BARTHOLEMEW
 104 AVENIDA MATEO APTB
 San Clemente, CA 92672

2008 GMC Canyon SLE

License # 36733S1

Inv Date: 2/27/2017 @ 8:57am

(949) 294-6291

VIN: 1GTDT19E988134239

Odom: 88502

Service Writer: Glen McDorman

Engine:L5 3.7L, 223cid, DOHC, GAS, FI, E

Color: BLACK

Status: Posted

Trans:

Mfg. Date:

Driver: BARTHOLEMEW, JOHN

Unit #

PO #

JON.BARTHOLEMEW84@GMAIL.COM

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
FRONT WHEEL HUBS SEIZED. CANNOT REMOVE ROTORS.					0.00
Labor Service - HUBS DISASSEMBLE FROM BEHIND KNUCKLE \$648 TO REMOVE & REPLACE 029					0.00
CUSTOMER STATES ENGINE SURGES & STALLS WHEN STARTING AFTER BEING PARKED FEW HOURS. INTERMITTENT.					2,015.68
Labor Service - CYLINDER #1 MISFIRE. SWAPPED COILS - NO CHANGE. SWAPPED SPARK PLUGS - NO CHANGE. REMOVED CYLINDER HEAD TO SUBLET FOR VALVE JOB DUE TO KNOWN PROBLEM WITH VALVE LEAKAGE. REINSTALLED CYLINDER HEAD & ROAD TESTED OK. MAXCARE AUTH #01921800 029					1,287.00
New	89060396	GASKET	1.00	210.98	210.98
New	11519306	BOLT	1.00	7.22	7.22
New	11609709	BOLT	12.00	6.50	78.00
New	11589234	BOLT	1.00	14.48	14.48
New	12565425	BOLT	1.00	6.50	6.50
New	12568766	SHOE	1.00	21.53	21.53
New	12590962	GUIDE	1.00	20.58	20.58
New	11519038	BOLT	4.00	6.73	26.92
New	BRAKLEEN	BRAKE & PARTS CLEANER	2.00	3.99	7.98
Sublet	CYLINDER HEAD	INSPECT & PRESSURE TEST CYLINDER HEAD. PERFORM VALVE JOB.	1.00	281.25	281.25
New	03328	COOLANT, OR, DEX COOL	2.00	26.62	53.24
CUSTOMER STATES WIPERS & FOG LIGHTS TURN ON BY THEMSELVES WHILE DRIVING INTERMITTENTLY					0.00
Labor Service - UNABLE TO REPRODUCE MALFUNCTION WHEN TESTED 029					0.00
CUSTOMER STATES ENGINE TEMP GAUGE GOES UP TO 3/4 ON WARM DAYS					446.16
Labor Service - REPLACED FAN CLUTCH PER MAXCARE AUTH #01921800 029					234.00
New	25948772	CLUTCH ASM-FAN BLADE	1.00	212.16	212.16
Customer requests that: PERFORM MINOR SERVICE SPECIAL					134.60
Labor Service - PERFORM MINOR SERVICE SPECIAL DUE EVERY 5,000 MILES INCLUDING CHANGE ENGINE OIL AND FILTER, ROTATE AND INFLATE TIRES, INSPECT AND MEASURE BRAKES, TOP OFF RECOMMENDED FLUIDS AS NEEDED, PERFORM MULTI-POINT VEHICLE INSPECTION OF UNDERCARRIAGE AND ENGINE BAY, ROAD TEST FOR PROPER PERFORMANCE. 029					45.00
New	5W30	5W/30 KENDALL SYNTHETIC BLEND	6.00	2.99	17.94
New	PG4006	FILTER, OIL	1.00	5.60	5.60
New	35 36 966	GM DRAIN PLUG GASKET	1.00	3.57	3.57
New	BRAKLEEN	BRAKE & PARTS CLEANER	1.00	2.99	2.99
Labor Service - REPLACE SPARK PLUGS 029					0.00
New	41-103	SPARK PLUG	5.00	11.90	59.50
Labor Service - CLEANED THROTTLE BODY N/C 029					0.00

Add On Charges Breakdown

Hazmat Waste 6.40

Notes

MAX CARE WARRANTY AUTH #01921800 BY DON KENNY 03/02/17 @ 7:43AM

Invoice # A18473

JOHN BARTHOLEMEW 2008 GMC Canyon SLE License # 36733S1 Inv Date: 2/27/2017 @ 8:57am

Vehicle Tire Information

Check Performed.

Tire Pressure PSI Left Front Right Front Left Rear Right Rear Checked By

<p>Warranty All repair work is warranted to be free from defects in materials and workmanship for a period 12 months or 12,000 miles.</p> <p>I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.</p> <p>X _____ Terms: We accept Cash, Visa, Master Card, American Express or Debit Cards. No Checks Accepted.</p> <p>X _____</p>	<p>Posted 3/15/17 6:41PM Visa 2,190.39 474.39</p>	<p>Invoice Summary</p> <table border="0"> <tr><td>Parts</td><td>695.95</td></tr> <tr><td>Labor</td><td>1,566.00</td></tr> <tr><td>Sublet</td><td>281.25</td></tr> <tr><td>Fluids</td><td>53.24</td></tr> <tr><td>Shop Supplies</td><td>2.00</td></tr> <tr><td>Add On Charges</td><td>6.40</td></tr> <tr><td colspan="2"> </td></tr> <tr><td>Sub Total</td><td>2,604.84</td></tr> <tr><td>Sales Tax (CA)</td><td>59.94</td></tr> <tr><td>Total</td><td>2,664.78</td></tr> </table>	Parts	695.95	Labor	1,566.00	Sublet	281.25	Fluids	53.24	Shop Supplies	2.00	Add On Charges	6.40			Sub Total	2,604.84	Sales Tax (CA)	59.94	Total	2,664.78
Parts	695.95																					
Labor	1,566.00																					
Sublet	281.25																					
Fluids	53.24																					
Shop Supplies	2.00																					
Add On Charges	6.40																					
Sub Total	2,604.84																					
Sales Tax (CA)	59.94																					
Total	2,664.78																					
<p>Page 2 of 2</p>	<p>Discard old parts Original Estimate: 76.23</p>	<p>Total 2,664.78</p>																				